AERODYNE SYSTEMS (PISA) PRODUCT SERVICE BULLETIN

Issue Date: 18July 2003

Bulletin Number 2003 07 2

Subject:

All Ripcord Pins used on:

- 1.) Naro Harness and Container Systems (Excluding RSL curved pin)
- 2.) Teardrop Harness and Container Systems Must conform to the Capewell Manufacturer Service Bulletin Number CW03-01, Issue Date 15 July 2003.

For clarity please consult your Rigger, Safety Officer or Aerodyne Systems.

Status:

Mandatory

Identification:

Part Number : P0138-00

: P0172-00 : P0172-10 : P0172-20 : P0180-00 : P0046-00 : P0046-10 : P0126-00

Date of manufacture : All reserve handles manufactured after

28 November 2001

Background:

Refer to Capewell Manufacturer Service Bulletin Number CW03-01 Issue Date 15 July 2003.

Service Bulletin:

Refer to Capewell Manufacturer Service Bulletin Number CW03-01 Issue Date 15 July 2003.

Compliance Date:

Immediate – 15 July 2003

Authority:

Aerodyne Systems
29 Duiker Road
Canelands
Tel (032) 533 0333
Fax (032) 533 0262
info-indianocean@aerodyne-int.com
www.aerodyne-int.com

Distribution:

Distribution includes but not limited to:

National Training and Safety Officer - PASA

PASA listserve

Drop Zone Safety Officers